

FEDERAL and AMERICAN EAGLE 45 AUTO PRODUCT SAFETY WARNING

UPDATED


Immediate Action Required

Certain lots of recently manufactured 45 Auto ammunition may contain an incorrect propellant charge. **Use of product from these lots may result in firearm damage and possible serious injury.**

DO NOT USE PRODUCT FROM THE FOLLOWING LOTS:

**38X628 through 38X765
38T401 through 38T414**

If you have in your possession any 45 Auto with the following brand names and part numbers, check to see if your ammunition package contains the above lots: American Eagle[®] (AE45A, AE45N1, or AE45A250), Champion[™] (WM5233), GoldMedal[®] (GM45B), Hi-Shok[®] (45C, 45D), Federal[®] Personal Defense[®] (C45C, C45D) and **Federal Premium[®] (P45HST1, P45HS2G, LE45T1)**. Example below:



THIS WARNING APPLIES ONLY TO THE LOTS LISTED ABOVE.

If you possess ammunition from any of these lots, or have questions concerning this warning, please contact us at **1-800-831-0850** or **1-800-322-2342** and ask for Product Service. Federal will provide replacement product and will cover the cost of returning the affected product.

We apologize for any inconvenience this may cause.